

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/PWD Dt: 23-01-1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Salman J. S.
St. Ann's School, Ayur,
Punalur.

31.99 x 9.24 x 3.30 - 4 Floors
27.50 x 9.50 x 2.00 - 2 Floors
46.20 x 12.60 x 3.00 - GF
46.20 x 9.30 x 3.00 - FF
46.20 x 9.30 x 3.00 - SF
2025-26

5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

NIL

Yes
Structure is sound for conducting classes under normal weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 15-07-2025 and found to be fit / unfit to conduct classes, for the period 2025-26 for the reasons stated above.

Place: Edamulackal
Date: 15-07-2025



Assistant Engineer
Edamulackal Grama Panchayat
Principal
St. Ann's School (CBSE)
Ayur, Kollam Dist.
Kerala - 691533

Annexure D

BUILDING SAFETY CERTIFICATE

No. 2

Dated: 15-07-2025

It is certified that the existing building St. Ann's School, Ayoor (name of the building or premises) at Ayoor (P.O), Punalur Taluk, Kollam (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	4	2	3			

The building is owned/occupied by St. Ann's School, Ayoor (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of LID, E.W. Section, Edamulackal G.P (Name of Department/ Govt.) on 15-07-2025 (date of inspection) in the presence of Sri. Juby Joseph, Principal (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 15-07-25 for a period of 02 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. School maintenance works have been done properly.
2. Under normal weather conditions, the structure is sound for conducting
- 3.
- 4.

Issued on 15-07-2025 at Edamulackal by Assistant Engineer

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.



Signature with Seal: Salman T.S

Name: Salman T.S

Designation: Assistant Engineer

Name & Address of Department/ Office: LID, E.W

Section, Edamulackal



Juby
PRINCIPAL
St. Ann's School (CBSE)
Ayur, Kollam Dist.
Kerala - 691533