

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Salman J. S.
St. Ann's School, Ayoor
Punalur.

31.99 x 9.24 x 3.30 M - 4 Floors.
27.50 x 9.50 x 3.00 M - 2 Floors.
46.20 x 12.60 x 3.00 M - GF
46.20 x 9.30 x 3.00 M - FF
46.20 x 9.20 x 3.00 M - SF
2026-27.

5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner

NIL

8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes


Yes.
The structure is sound for conducting classes under normal weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Remark: This certificate is issued on the basis that the Item No: 9 in checklist must be certified by an approved workman and the same be recorded separately and kept with school head within one month of this Report.

certified that the school building was inspected by me on 08-06-2026 and found to be fit / unfit to conduct classes, for the period 2026-27. for the reasons stated above.

Place Edamulakkal.
Date 08-06-2026



[Signature]
ASSISTANT ENGINEER
LID & EW Section
Edamulakkal Gram Panchayat
Assistant Engineer

500/2-6-13
[Signature]
MANAGER
St. Ann's School (CBSE)
Ayoor, Kollam (Dist)
Kerala-691533

[Signature]
PRINCIPAL
St. Ann's School (CBSE)
Ayur, Kollam Dist.
Kerala - 691533

Annexure D

BUILDING SAFETY CERTIFICATE

No. 1

Dated: 08/06/2026

It is certified that the existing building St. Ann's School, Ayoor (name of the building or premises) at Ayoor (P.O), Punalur Taluk, Kollam (address) is having block(s)/floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	4	2	3			

The building is owned/occupied by St. Ann's School, Ayoor (name of the Institution) have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of LIDSEW Section, Edamulackal Gramapanchayat (Name of Department/Govt.) on 08/06/2026 (date of inspection) in the presence of Sri. Juby Joseph, Principal (name and address of the Manager/Secretary or representative) and that the building/premises is fit for occupancy for running school with effect from 08/06/2026 for a period of One years. In accordance with rule and subject to compliance of the specific conditions as appended

1. School Maintenance works have been done properly.
2. Under Normal weather conditions, the structure is found fit for conducting classes
- 3.
- 4.

Issued on 08/06/2026 at Edamulackal by Assistant Engineer.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.



Signature with Seal: [Signature]

Name: Salman J

Designation: Assistant Engineer

Name & Address of Department/Office: LIDSEW Section, Edamulackal.

S. Jose
MANAGER
 St. Ann's School (CBSE)
 Ayoor, Kollam (Dist)
 Kerala-691533

Juby
PRINCIPAL
 St. Ann's School (CBSE)
 Ayur, Kollam Dist.
 Kerala - 691533